



LM Guide SRS | SRS7WGSSS+50LM (G10g10)

Bearing No. SRS7WGSSS+50LM (G10g10)

MN	No connection
GX2	SRS7WGS
VER	10.00