



LM Guide SHW | SHW12CR1SSM+70LM (G15g15)

Bearing No. SHW12CR1SSM+70LM (G15g15)

MN	No connection
GX2	SHW12CRM